

Peli Products S.L.U. ("Peli") will stop carrying parts for and servicing selected Peli RALS products listed in the table below. Peli will make every effort to support customers' requirements for colours but it may need to substitute alternatives in order to repair the products up to the repair/service cutoff date. Please contact customer service for additional support.

### AFFECTED MODELS

9420 RALS Repair/Service Cutoff Date 30/09/2022	9430 RALS Repair/Service Cutoff Dates Gen. I: 31/12/2018 Gen. II: 28/02/2020	9435 RALS Repair/Service Cutoff Date 31/08/2022
9440 RALS Repair/Service Cutoff Date Gen. I: 31/07/2020	9450 RALS Repair/Service Cutoff Date 31/10/2017	9460 RALS Repair/Service Cutoff Dates Gen. I: 28/02/2017 Gen. II: 31/10/2021
9460RS RALS Repair/Service Cutoff Date 31/10/2021	9470 RALS Repair/Service Cutoff Dates Gen. I: 30/06/2020 Gen. II: 31/10/2021	9470RS RALS Repair/Service Cutoff Date 31/10/2021

\*Purchaser shall pay for handling, return freight and repairs at Peli's prevailing rates for out-of-warranty and after-warranty repairs.